



Email: rma@mybacharach.com
 Phone: 800-736-4666 (Select 2 then select 1)
 Fax: 724-334-5001

Effective 1/1/2018

Please call for instrument part numbers not included in this list. Service may no longer be available or we can suggest a replacement.

** 24 hour Priority Service is only available for items listed below. Priority Service orders MUST (1) include a pre-approved amount, (2) include the RMA paperwork and (3) a PRIORITY label on the outside of the package. Returns received without this information will cause delays in processing your order. 24 hrs begins when the instrument is received at our facility during regular business hours Monday through Friday. Return shipping and handling charges will be added to the order unless directed to ship collect or billed to a 3rd party account in which case only a handling charge will apply. AQMD testing is not available for Priority Service. **

Instrument Information		Repair Fees				Optional		Current	
Part Number	Model	Functional Test (Min)	Standard Calibration Only (Min)	Standard Calibration Plus 1 Sensor (Typical)	Not to Exceed (Max Preapproved)	NIST Certificate (Before & After Readings)	**24 Hour Priority Service	Suggested Replacement	With Printer
0011-7032	FYRITE CLASSIC (20% CO2)	N/A	\$205.00	N/A	\$205.00	\$100.00	N/A	N/A	N/A
0011-7034	FYRITE CLASSIC (60% CO2)	N/A	\$205.00	N/A	\$205.00	\$100.00	N/A	N/A	N/A
0011-7036	FYRITE CLASSIC (21% O2)	N/A	\$205.00	N/A	\$205.00	\$100.00	N/A	N/A	N/A
0011-7042	FYRITE CLASSIC (7% CO2)	N/A	\$205.00	N/A	\$205.00	\$100.00	N/A	N/A	N/A
0011-7044	FYRITE CLASSIC (7% O2)	N/A	\$205.00	N/A	\$205.00	\$100.00	N/A	N/A	N/A
0019-7051	LEAKATOR-10	\$60.00	N/A	\$113.00	\$160.00	N/A	N/A	N/A	N/A
0019-7060	SNIFIT 50	N/A	\$93.00	\$173.00	\$199.00	\$100.00	\$50.00	N/A	N/A
0019-7067	INFORMANT 2	\$60.00	N/A	\$103.00	\$224.00	N/A	N/A	N/A	N/A
0019-7075	LEAKATOR JR	\$60.00	N/A	\$113.00	\$160.00	N/A	N/A	N/A	N/A
0019-7112	TRUPOINTE	\$60.00	N/A	\$105.00	\$125.00	N/A	N/A	N/A	N/A
0019-7147	MONOXOR III	N/A	\$145.00	\$270.00	\$314.00	\$100.00	\$50.00	0019-8117	0019-8118
0019-7148	OXOR III (Limited Repair)	Obsolete Model - Consider Replacing			\$319.00	\$100.00	\$50.00	0024-8510	N/A
0019-7163	MONOXOR PLUS	N/A	\$145.00	\$270.00	\$314.00	\$100.00	\$50.00	N/A	N/A
0024-7181	PCA-10 EUROPEAN (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8460	0024-8467
0024-7182	PCA-15 EUROPEAN (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8460	0024-8467
0024-7183	PCA-20 EUROPEAN (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8460	0024-8467
0024-7184	PCA-25 EUROPEAN (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8460	0024-8467
0024-7185	PCA-30 EUROPEAN (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8464	0024-8471
0024-7186	PCA-35 EUROPEAN (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8445	0024-8452
0024-7187	PCA-10 (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8440	0024-8447
0024-7188	PCA-15 (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8440	0024-8447
0024-7189	PCA-20 (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8440	0024-8447
0024-7190	PCA-25 (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8440	0024-8447
0024-7191	PCA-30 (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8445	0024-8452



Email: rma@mybacharach.com
 Phone: 800-736-4666 (Select 2 then select 1)
 Fax: 724-334-5001

Effective 1/1/2018

Please call for instrument part numbers not included in this list. Service may no longer be available or we can suggest a replacement.

** 24 hour Priority Service is only available for items listed below. Priority Service orders MUST (1) include a pre-approved amount, (2) include the RMA paperwork and (3) a PRIORITY label on the outside of the package. Returns received without this information will cause delays in processing your order. 24 hrs begins when the instrument is received at our facility during regular business hours Monday through Friday. Return shipping and handling charges will be added to the order unless directed to ship collect or billed to a 3rd party account in which case only a handling charge will apply. AQMD testing is not available for Priority Service. **

Instrument Information		Repair Fees				Optional		Current	
Part Number	Model	Functional Test (Min)	Standard Calibration Only (Min)	Standard Calibration Plus 1 Sensor (Typical)	Not to Exceed (Max Preapproved)	NIST Certificate (Before & After Readings)	**24 Hour Priority Service	Suggested Replacement	With Printer
0024-7192	PCA-35 (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8445	0024-8452
0024-7210	PCA-12 (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8440	0024-8447
0024-7211	PCA-40 (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8440	0024-8447
0024-7212	PCA-45 (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8440	0024-8447
0024-7213	PCA-50 (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8440	0024-8447
0024-7214	PCA-55 (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8440	0024-8447
0024-7215	PCA-60 (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8445	0024-8452
0024-7216	PCA-65 (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8445	0024-8452
0024-7220	FYRITE PRO 125 - EU (Limited Repair)	Obsolete Model - Consider Replacing			\$719.00	\$100.00	\$50.00	0024-8521	0024-8520
0024-7221	ECA450	N/A	\$345.00	\$655.00	\$1,369.00	\$100.00	\$50.00	N/A	N/A
0024-7229	ECA450	N/A	\$345.00	\$655.00	\$1,369.00	\$100.00	\$50.00	N/A	N/A
0024-7231	FYRITE TECH 50 (Limited Repair)	Obsolete Model - Consider Replacing			\$470.00	\$100.00	\$50.00	0024-8510	0024-8512
0024-7232	FYRITE TECH 60 (Limited Repair)	Obsolete Model - Consider Replacing			\$470.00	\$100.00	\$50.00	0024-8511	0024-8512
0024-7233	FYRITE TECH 50 - EU (Limited Repair)	Obsolete Model - Consider Replacing			\$470.00	\$100.00	\$50.00	0024-8513	0024-8514
0024-7234	FYRITE TECH 60EP - EU (Limited Repair)	Obsolete Model - Consider Replacing			\$470.00	\$100.00	\$50.00	0024-8513	0024-8514
0024-7236	FYRITE TECH 60P (Limited Repair)	Obsolete Model - Consider Replacing			\$470.00	\$100.00	\$50.00	0024-8511	0024-8512
0024-7259	FYRITE PRO-110 (Limited Repair)	Obsolete Model - Consider Replacing			\$719.00	\$100.00	\$50.00	0024-8517	0024-8518
0024-7260	FYRITE PRO-120 (Limited Repair)	Obsolete Model - Consider Replacing			\$719.00	\$100.00	\$50.00	0024-8517	0024-8518
0024-7268	FYRITE PRO-125 (Limited Repair)	Obsolete Model - Consider Replacing			\$719.00	\$100.00	\$50.00	0024-8517	0024-8518
0024-7269	FYRITE PRO-105 (Limited Repair)	Obsolete Model - Consider Replacing			\$719.00	\$100.00	\$50.00	0024-8517	0024-8518
0024-7270	FYRITE PRO-100 (Limited Repair)	Obsolete Model - Consider Replacing			\$719.00	\$100.00	\$50.00	0024-8517	0024-8518
0024-7275	FYRITE PRO 125F (Limited Repair)	Obsolete Model - Consider Replacing			\$719.00	\$100.00	\$50.00	0024-8521	0024-8520
0024-7276	FYRITE PRO 125E - EU (Limited Repair)	Obsolete Model - Consider Replacing			\$719.00	\$100.00	\$50.00	0024-8521	0024-8520
0024-7279	FYRITE PRO 125I (Limited Repair)	Obsolete Model - Consider Replacing			\$719.00	\$100.00	\$50.00	0024-8521	0024-8520



Email: rma@mybacharach.com
 Phone: 800-736-4666 (Select 2 then select 1)
 Fax: 724-334-5001

Effective 1/1/2018

Please call for instrument part numbers not included in this list. Service may no longer be available or we can suggest a replacement.

** 24 hour Priority Service is only available for items listed below. Priority Service orders MUST (1) include a pre-approved amount, (2) include the RMA paperwork and (3) a PRIORITY label on the outside of the package. Returns received without this information will cause delays in processing your order. 24 hrs begins when the instrument is received at our facility during regular business hours Monday through Friday. Return shipping and handling charges will be added to the order unless directed to ship collect or billed to a 3rd party account in which case only a handling charge will apply. AQMD testing is not available for Priority Service. **

Instrument Information		Repair Fees				Optional		Current	
Part Number	Model	Functional Test (Min)	Standard Calibration Only (Min)	Standard Calibration Plus 1 Sensor (Typical)	Not to Exceed (Max Preapproved)	NIST Certificate (Before & After Readings)	**24 Hour Priority Service	Suggested Replacement	With Printer
0024-7281	PCA-10 EU (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8460	0024-8467
0024-7282	PCA-15 EU (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8460	0024-8467
0024-7283	PCA-20 EU (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8460	0024-8467
0024-7284	PCA-25 EU (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8460	0024-8467
0024-7285	PCA-30 EU (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8464	0024-8471
0024-7286	PCA-35 EU (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8464	0024-8471
0024-7289	ECA450	N/A	\$345.00	\$655.00	\$1,369.00	\$100.00	\$50.00	N/A	N/A
0024-7301	PCA2-225 (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8440	0024-8447
0024-7302	PCA2-235 (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8441	0024-8448
0024-7303	PCA2-245 (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8442	0024-8449
0024-7304	PCA2-255 (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8443	0024-8450
0024-7305	PCA2-265 (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8444	0024-8451
0024-7306	PCA2-275 (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8445	0024-8452
0024-7307	PCA2-285 (Limited Repair)	Obsolete Model - Consider Replacing			\$827.00	\$100.00	\$50.00	0024-8446	0024-8453
0024-7308	FYRITE INSIGHT	N/A	\$145.00	\$270.00	\$714.00	\$100.00	\$50.00	0024-8515	0024-8516
0024-7309	FYRITE INSIGHT - SIEGERT	N/A	\$145.00	\$270.00	\$714.00	\$100.00	\$50.00	0024-8519	0024-8520
0024-7311	FYRITE INSIGHT - DANISH	N/A	\$145.00	\$270.00	\$714.00	\$100.00	\$50.00	0024-8519	0024-8520
0024-7320	PCA3-225	N/A	\$185.00	\$400.00	\$724.00	\$100.00	\$50.00	N/A	N/A
0024-7321	PCA3-235	N/A	\$185.00	\$400.00	\$724.00	\$100.00	\$50.00	N/A	N/A
0024-7322	PCA3-245	N/A	\$185.00	\$400.00	\$724.00	\$100.00	\$50.00	N/A	N/A
0024-7323	PCA3-255	N/A	\$185.00	\$400.00	\$724.00	\$100.00	\$50.00	N/A	N/A
0024-7324	PCA3-265	N/A	\$185.00	\$400.00	\$724.00	\$100.00	\$50.00	N/A	N/A
0024-7325	PCA3-275	N/A	\$185.00	\$400.00	\$724.00	\$100.00	\$50.00	N/A	N/A
0024-7326	PCA3-285	N/A	\$185.00	\$400.00	\$724.00	\$100.00	\$50.00	N/A	N/A



Email: rma@mybacharach.com
 Phone: 800-736-4666 (Select 2 then select 1)
 Fax: 724-334-5001

Effective 1/1/2018

Please call for instrument part numbers not included in this list. Service may no longer be available or we can suggest a replacement.

** 24 hour Priority Service is only available for items listed below. Priority Service orders MUST (1) include a pre-approved amount, (2) include the RMA paperwork and (3) a PRIORITY label on the outside of the package. Returns received without this information will cause delays in processing your order. 24 hrs begins when the instrument is received at our facility during regular business hours Monday through Friday. Return shipping and handling charges will be added to the order unless directed to ship collect or billed to a 3rd party account in which case only a handling charge will apply. AQMD testing is not available for Priority Service. **

Instrument Information		Repair Fees				Optional		Current	
Part Number	Model	Functional Test (Min)	Standard Calibration Only (Min)	Standard Calibration Plus 1 Sensor (Typical)	Not to Exceed (Max Preapproved)	NIST Certificate (Before & After Readings)	**24 Hour Priority Service	Suggested Replacement	With Printer
0024-7327	PCA3 DANISH	N/A	\$185.00	\$400.00	\$724.00	\$100.00	\$50.00	N/A	N/A
0024-7328	PCA3-295	N/A	\$185.00	\$400.00	\$724.00	\$100.00	\$50.00	N/A	N/A
0024-7330	PCA3-225 - SIEGERT	N/A	\$185.00	\$400.00	\$724.00	\$100.00	\$50.00	N/A	N/A
0024-7331	PCA3-235 - SIEGERT	N/A	\$185.00	\$400.00	\$724.00	\$100.00	\$50.00	N/A	N/A
0024-7332	PCA3-245 - SIEGERT	N/A	\$185.00	\$400.00	\$724.00	\$100.00	\$50.00	N/A	N/A
0024-7333	PCA3-255 - SEIGERT	N/A	\$185.00	\$400.00	\$724.00	\$100.00	\$50.00	N/A	N/A
0024-7334	PCA3-265 - SEIGERT	N/A	\$185.00	\$400.00	\$724.00	\$100.00	\$50.00	N/A	N/A
0024-7335	PCA3-275 - SEIGERT	N/A	\$185.00	\$400.00	\$724.00	\$100.00	\$50.00	N/A	N/A
0024-7336	PCA3-285 - SEIGERT	N/A	\$185.00	\$400.00	\$724.00	\$100.00	\$50.00	N/A	N/A
0024-7337	PCA3-295 - SEIGERT	N/A	\$185.00	\$400.00	\$724.00	\$100.00	\$50.00	N/A	N/A
0024-7340	FYRITE INTECH	N/A	\$145.00	\$270.00	\$354.00	\$100.00	\$50.00	N/A	N/A
0024-7341	FYRITE INTECH	N/A	\$145.00	\$270.00	\$354.00	\$100.00	\$50.00	N/A	N/A
0024-7342	FYRITE INTECH - EUROPEAN	N/A	\$145.00	\$270.00	\$354.00	\$100.00	\$50.00	N/A	N/A
0024-7343	FYRITE INSIGHT PLUS	N/A	\$145.00	\$270.00	\$714.00	\$100.00	\$50.00	N/A	N/A
0024-7344	FYRITE INSIGHT PLUS	N/A	\$145.00	\$270.00	\$714.00	\$100.00	\$50.00	N/A	N/A
0024-7345	FYRITE INSIGHT PLUS - EUROPEAN	N/A	\$145.00	\$270.00	\$714.00	\$100.00	\$50.00	N/A	N/A
0024-7346	FYRITE INSIGHT PLUS - EUROPEAN	N/A	\$145.00	\$270.00	\$714.00	\$100.00	\$50.00	N/A	N/A
0024-7349	FYRITE INSIGHT PLUS - DANISH	N/A	\$145.00	\$270.00	\$714.00	\$100.00	\$50.00	N/A	N/A
2000-3600	FM3600 (Limited Repair)	Obsolete Model - Consider Replacing			\$999.00	N/A	N/A	2020-8000	N/A
2000-3611	FM3600 (Limited Repair)	Obsolete Model - Consider Replacing			\$999.00	N/A	N/A	2020-8001	N/A
2000-3700	FM3700 (Limited Repair)	Obsolete Model - Consider Replacing			\$999.00	N/A	N/A	2020-8000	N/A
2000-3701	FM3700 (Limited Repair)	Obsolete Model - Consider Replacing			\$1,099.00	N/A	N/A	2020-8001	N/A
2020-8000	ECO2020	Return for Estimate			\$359.00	N/A	N/A	N/A	N/A
2020-8001	ECO2020	Return for Estimate			\$359.00	N/A	N/A	N/A	N/A



Email: rma@mybacharach.com
 Phone: 800-736-4666 (Select 2 then select 1)
 Fax: 724-334-5001

Effective 1/1/2018

Please call for instrument part numbers not included in this list. Service may no longer be available or we can suggest a replacement.

** 24 hour Priority Service is only available for items listed below. Priority Service orders MUST (1) include a pre-approved amount, (2) include the RMA paperwork and (3) a PRIORITY label on the outside of the package. Returns received without this information will cause delays in processing your order. 24 hrs begins when the instrument is received at our facility during regular business hours Monday through Friday. Return shipping and handling charges will be added to the order unless directed to ship collect or billed to a 3rd party account in which case only a handling charge will apply. AQMD testing is not available for Priority Service. **

Instrument Information		Repair Fees				Optional		Current	
Part Number	Model	Functional Test (Min)	Standard Calibration Only (Min)	Standard Calibration Plus 1 Sensor (Typical)	Not to Exceed (Max Preapproved)	NIST Certificate (Before & After Readings)	**24 Hour Priority Service	Suggested Replacement	With Printer
3015-0456	H10G	Obsolete Model - Consider Replacing			N/A	N/A	N/A	3015-8004	N/A
3015-0462	H10G	Obsolete Model - Consider Replacing			N/A	N/A	N/A	3015-8004	N/A
3015-0480	H10G	Obsolete Model - Consider Replacing			N/A	N/A	N/A	3015-8004	N/A
3015-0627	H10PM (Limited Repair)	Obsolete Model - Consider Replacing			\$304.00	N/A	\$50.00	3015-8004	N/A
3015-0630	H10PM (Limited Repair)	Obsolete Model - Consider Replacing			\$304.00	N/A	\$50.00	3015-8004	N/A
3015-0636	H10PM (Limited Repair)	Obsolete Model - Consider Replacing			\$304.00	N/A	\$50.00	3015-8004	N/A
3015-4200	SINGLE-ZONE HGMSZ	N/A	\$175.00	N/A	\$1,099.00	\$100.00	N/A	N/A	N/A
3015-4316	SINGLE-ZONE HGMSZ	N/A	\$175.00	N/A	\$1,099.00	\$100.00	N/A	N/A	N/A
3015-4348	H25IR	N/A	\$399.00	N/A	\$1,013.00	\$100.00	\$50.00	H25IR-PRO	N/A
3015-4484	PORTABLE GAS MONITOR-HGM	N/A	\$195.00	N/A	\$1,099.00	\$100.00	N/A	N/A	N/A
3015-4790	PORTABLE GAS MONITOR-N2O	N/A	\$195.00	N/A	\$1,099.00	\$100.00	N/A	N/A	N/A
3015-5043	MULTI-ZONE HGMMZ	N/A	\$195.00	N/A	\$1,099.00	\$100.00	N/A	N/A	N/A
3015-5044	MULTI-ZONE HGMMZ	N/A	\$195.00	N/A	\$1,099.00	\$100.00	N/A	N/A	N/A
3015-5045	MULTI-ZONE HGMMZ	N/A	\$195.00	N/A	\$1,099.00	\$100.00	N/A	N/A	N/A
3015-5046	MULTI-ZONE HGMMZ	N/A	\$195.00	N/A	\$1,099.00	\$100.00	N/A	N/A	N/A
3015-5138	MZ REMOTE DISPLAY HGMRD	N/A	N/A	N/A	\$699.00	N/A	N/A	N/A	N/A
3015-5200	MULTI-ZONE HGMMZ	N/A	\$195.00	N/A	\$1,099.00	\$100.00	N/A	N/A	N/A
3015-5201	MULTI-ZONE HGMMZ	N/A	\$195.00	N/A	\$1,099.00	\$100.00	N/A	N/A	N/A
3015-5202	MULTI-ZONE HGMMZ	N/A	\$195.00	N/A	\$1,099.00	\$100.00	N/A	N/A	N/A
3015-5203	MULTI-ZONE HGMMZ	N/A	\$195.00	N/A	\$1,099.00	\$100.00	N/A	N/A	N/A
3015-5211	MULTI-ZONE HGMMZ	N/A	\$195.00	N/A	\$1,099.00	\$100.00	N/A	N/A	N/A
3015-5213	MULTI-ZONE HGMMZ	N/A	\$195.00	N/A	\$1,099.00	\$100.00	N/A	N/A	N/A
3015-5260	H25IR	N/A	\$399.00	N/A	\$1,099.00	\$100.00	\$50.00	H25IR-PRO	N/A
3015-5330	MULTI-ZONE HGMMZ	N/A	\$195.00	N/A	\$1,099.00	\$100.00	N/A	N/A	N/A



Email: rma@mybacharach.com
 Phone: 800-736-4666 (Select 2 then select 1)
 Fax: 724-334-5001

Effective 1/1/2018

Please call for instrument part numbers not included in this list. Service may no longer be available or we can suggest a replacement.

** 24 hour Priority Service is only available for items listed below. Priority Service orders MUST (1) include a pre-approved amount, (2) include the RMA paperwork and (3) a PRIORITY label on the outside of the package. Returns received without this information will cause delays in processing your order. 24 hrs begins when the instrument is received at our facility during regular business hours Monday through Friday. Return shipping and handling charges will be added to the order unless directed to ship collect or billed to a 3rd party account in which case only a handling charge will apply. AQMD testing is not available for Priority Service. **

Instrument Information		Repair Fees				Optional		Current	
Part Number	Model	Functional Test (Min)	Standard Calibration Only (Min)	Standard Calibration Plus 1 Sensor (Typical)	Not to Exceed (Max Preapproved)	NIST Certificate (Before & After Readings)	**24 Hour Priority Service	Suggested Replacement	With Printer
3015-5333	MULTI-ZONE HGMMZ	N/A	\$195.00	N/A	\$1,099.00	\$100.00	N/A	N/A	N/A
3015-5560	MULTI-ZONE HGMMZ	N/A	\$195.00	N/A	\$1,099.00	\$100.00	N/A	N/A	N/A
3015-5570	MULTI-ZONE HGMMZ	N/A	\$195.00	N/A	\$1,099.00	\$100.00	N/A	N/A	N/A
3015-5600	H25IR-PRO	N/A	\$399.00	N/A	\$1,099.00	\$100.00	\$50.00	N/A	N/A
3015-5696	PORTABLE GAS MONITOR-HGM	N/A	\$195.00	N/A	\$1,099.00	\$100.00	N/A	N/A	N/A
3015-5720	PORTABLE GAS MONITOR-HGM	N/A	\$195.00	N/A	\$1,099.00	\$100.00	N/A	N/A	N/A
3015-5732	MULTI-ZONE HGMMZ	N/A	\$195.00	N/A	\$1,099.00	\$100.00	N/A	N/A	N/A
3015-5734	MULTI-ZONE HGMMZ	N/A	\$195.00	N/A	\$1,099.00	\$100.00	N/A	N/A	N/A
3015-5751	PORTABLE GAS MONITOR-CO2	N/A	\$195.00	N/A	\$1,099.00	\$100.00	N/A	N/A	N/A
3015-5835	H25IR-PRO	N/A	\$399.00	N/A	\$1,099.00	\$100.00	\$50.00	N/A	N/A
3015-7000	H10PRO	\$60.00	N/A	\$225.00	\$304.00	N/A	\$50.00	N/A	N/A
3019-8101	MULTI-ZONE HGMMZ	N/A	\$195.00	N/A	\$1,099.00	\$100.00	N/A	N/A	N/A
5110-0100	ODOROMETER	N/A	\$275.00	N/A	\$329.00	\$100.00	N/A	N/A	N/A
5110-0200	ODOROMETER	N/A	\$275.00	N/A	\$329.00	\$100.00	N/A	N/A	N/A