



Effective 1/1/2019 Rev. 0

Please call for instrument part numbers not included in this list. Service may no longer be available or we can suggest a replacement.

** 24 hour Priority Service is only available for items listed below. Priority Service orders MUST (1) include a pre-approved amount, (2) include the RMA paperwork and (3) a PRIORITY label on the outside of the package. Returns received without this information will cause delays in processing your order. 24 hrs begins when the instrument is received at our facility during regular business hours Monday through Friday. Return shipping and handling charges will be added to the order unless directed to ship collect or billed to a 3rd party account in which case only a handling charge will apply. AQMD testing is not available for Priority Service. **

| Instrument Information | | Repair Fees | | | | Optional | | Current | |
|------------------------|----------------------------------|-------------------------------------|---------------------------------|--|---------------------------------|--|----------------------------|-----------------------|--------------|
| Part Number | Model | Functional Test (Min) | Standard Calibration Only (Min) | Standard Calibration Plus 1 Sensor (Typical) | Not to Exceed (Max Preapproved) | NIST Certificate (Before & After Readings) | **24 Hour Priority Service | Suggested Replacement | With Printer |
| 0011-7032 | FYRITE CLASSIC (20% CO2) | N/A | \$225.00 | N/A | \$225.00 | \$100.00 | N/A | N/A | N/A |
| 0011-7034 | FYRITE CLASSIC (60% CO2) | N/A | \$225.00 | N/A | \$225.00 | \$100.00 | N/A | N/A | N/A |
| 0011-7036 | FYRITE CLASSIC (21% O2) | N/A | \$225.00 | N/A | \$225.00 | \$100.00 | N/A | N/A | N/A |
| 0011-7042 | FYRITE CLASSIC (7% CO2) | N/A | \$225.00 | N/A | \$225.00 | \$100.00 | N/A | N/A | N/A |
| 0011-7044 | FYRITE CLASSIC (7% O2) | N/A | \$225.00 | N/A | \$225.00 | \$100.00 | N/A | N/A | N/A |
| 0019-7051 | LEAKATOR-10 | \$60.00 | N/A | \$113.00 | \$160.00 | N/A | N/A | N/A | N/A |
| 0019-7060 | SNIFIT 50 | N/A | \$93.00 | \$173.00 | \$199.00 | \$100.00 | \$50.00 | N/A | N/A |
| 0019-7067 | INFORMANT 2 | \$60.00 | N/A | \$103.00 | \$224.00 | N/A | N/A | N/A | N/A |
| 0019-7075 | LEAKATOR JR | \$60.00 | N/A | \$113.00 | \$160.00 | N/A | N/A | N/A | N/A |
| 0019-7112 | TRUPOINTE | \$60.00 | N/A | \$105.00 | \$125.00 | N/A | N/A | N/A | N/A |
| 0019-7147 | MONOXOR III | N/A | \$150.00 | \$275.00 | \$320.00 | \$100.00 | \$50.00 | 0019-8117 | 0019-8118 |
| 0019-7148 | OXOR III (Limited Repair) | Obsolete Model - Consider Replacing | | | \$320.00 | \$100.00 | \$50.00 | 0024-8510 | N/A |
| 0019-7163 | MONOXOR PLUS | N/A | \$145.00 | \$270.00 | \$315.00 | \$100.00 | \$50.00 | N/A | N/A |
| 0024-7181 | PCA-10 EUROPEAN (Limited Repair) | Last Day of Service June 30, 2019 | | | \$850.00 | \$100.00 | \$50.00 | 0024-8513 | 0024-8514 |
| 0024-7182 | PCA-15 EUROPEAN (Limited Repair) | Last Day of Service June 30, 2019 | | | \$850.00 | \$100.00 | \$50.00 | 0024-8521 | 0024-8522 |
| 0024-7183 | PCA-20 EUROPEAN (Limited Repair) | Last Day of Service June 30, 2019 | | | \$850.00 | \$100.00 | \$50.00 | 0024-8513 | 0024-8514 |
| 0024-7184 | PCA-25 EUROPEAN (Limited Repair) | Last Day of Service June 30, 2019 | | | \$850.00 | \$100.00 | \$50.00 | 0024-8521 | 0024-8522 |
| 0024-7185 | PCA-30 EUROPEAN (Limited Repair) | Last Day of Service June 30, 2019 | | | \$850.00 | \$100.00 | \$50.00 | 2411-1110 | 2411-1112 |
| 0024-7186 | PCA-35 EUROPEAN (Limited Repair) | Last Day of Service June 30, 2019 | | | \$850.00 | \$100.00 | \$50.00 | 2411-1110 | 2411-1112 |
| 0024-7187 | PCA-10 (Limited Repair) | Last Day of Service June 30, 2019 | | | \$850.00 | \$100.00 | \$50.00 | 0024-8523 | 0024-8512 |
| 0024-7188 | PCA-15 (Limited Repair) | Last Day of Service June 30, 2019 | | | \$850.00 | \$100.00 | \$50.00 | 0024-8517 | 0024-8518 |
| 0024-7189 | PCA-20 (Limited Repair) | Last Day of Service June 30, 2019 | | | \$850.00 | \$100.00 | \$50.00 | 0024-8523 | 0024-8512 |
| 0024-7190 | PCA-25 (Limited Repair) | Last Day of Service June 30, 2019 | | | \$850.00 | \$100.00 | \$50.00 | 0024-8517 | 0024-8518 |
| 0024-7191 | PCA-30 (Limited Repair) | Last Day of Service June 30, 2019 | | | \$850.00 | \$100.00 | \$50.00 | 2411-1110 | 2411-1112 |



Effective 1/1/2019 Rev. 0

Please call for instrument part numbers not included in this list. Service may no longer be available or we can suggest a replacement.

** 24 hour Priority Service is only available for items listed below. Priority Service orders MUST (1) include a pre-approved amount, (2) include the RMA paperwork and (3) a PRIORITY label on the outside of the package. Returns received without this information will cause delays in processing your order. 24 hrs begins when the instrument is received at our facility during regular business hours Monday through Friday. Return shipping and handling charges will be added to the order unless directed to ship collect or billed to a 3rd party account in which case only a handling charge will apply. AQMD testing is not available for Priority Service. **

| Instrument Information | | Repair Fees | | | | Optional | | Current | |
|------------------------|--|-------------------------------------|---------------------------------|--|---------------------------------|--|----------------------------|-----------------------|--------------|
| Part Number | Model | Functional Test (Min) | Standard Calibration Only (Min) | Standard Calibration Plus 1 Sensor (Typical) | Not to Exceed (Max Preapproved) | NIST Certificate (Before & After Readings) | **24 Hour Priority Service | Suggested Replacement | With Printer |
| 0024-7192 | PCA-35 (Limited Repair) | Last Day of Service June 30, 2019 | | | \$850.00 | \$100.00 | \$50.00 | 2411-1110 | 2411-1112 |
| 0024-7210 | PCA-12 (Limited Repair) | Last Day of Service June 30, 2019 | | | \$850.00 | \$100.00 | \$50.00 | 0024-8517 | 0024-8518 |
| 0024-7211 | PCA-40 (Limited Repair) | Last Day of Service June 30, 2019 | | | \$850.00 | \$100.00 | \$50.00 | 0024-8523 | 0024-8512 |
| 0024-7212 | PCA-45 (Limited Repair) | Last Day of Service June 30, 2019 | | | \$850.00 | \$100.00 | \$50.00 | 0024-8517 | 0024-8518 |
| 0024-7213 | PCA-50 (Limited Repair) | Last Day of Service June 30, 2019 | | | \$850.00 | \$100.00 | \$50.00 | 0024-8523 | 0024-8512 |
| 0024-7214 | PCA-55 (Limited Repair) | Last Day of Service June 30, 2019 | | | \$850.00 | \$100.00 | \$50.00 | 0024-8517 | 0024-8518 |
| 0024-7215 | PCA-60 (Limited Repair) | Last Day of Service June 30, 2019 | | | \$850.00 | \$100.00 | \$50.00 | 2411-1110 | 2411-1112 |
| 0024-7216 | PCA-65 (Limited Repair) | Last Day of Service June 30, 2019 | | | \$850.00 | \$100.00 | \$50.00 | 2411-1110 | 2411-1112 |
| 0024-7220 | FYRITE PRO 125 - EU (Limited Repair) | Obsolete Model - Consider Replacing | | | \$725.00 | \$100.00 | \$50.00 | 0024-8521 | 0024-8520 |
| 0024-7221 | ECA450 | N/A | \$350.00 | \$660.00 | \$1,400.00 | \$100.00 | \$50.00 | N/A | N/A |
| 0024-7229 | ECA450 | N/A | \$350.00 | \$660.00 | \$1,400.00 | \$100.00 | \$50.00 | N/A | N/A |
| 0024-7231 | FYRITE TECH 50 (Limited Repair) | Last Day of Service June 30, 2019 | | | \$475.00 | \$100.00 | \$50.00 | 0024-8510 | 0024-8512 |
| 0024-7232 | FYRITE TECH 60 (Limited Repair) | Last Day of Service June 30, 2019 | | | \$475.00 | \$100.00 | \$50.00 | 0024-8511 | 0024-8512 |
| 0024-7233 | FYRITE TECH 50 - EU (Limited Repair) | Last Day of Service June 30, 2019 | | | \$475.00 | \$100.00 | \$50.00 | 0024-8513 | 0024-8514 |
| 0024-7234 | FYRITE TECH 60EP - EU (Limited Repair) | Last Day of Service June 30, 2019 | | | \$475.00 | \$100.00 | \$50.00 | 0024-8513 | 0024-8514 |
| 0024-7236 | FYRITE TECH 60P (Limited Repair) | Last Day of Service June 30, 2019 | | | \$475.00 | \$100.00 | \$50.00 | 0024-8511 | 0024-8512 |
| 0024-7259 | FYRITE PRO-110 (Limited Repair) | Obsolete Model - Consider Replacing | | | \$725.00 | \$100.00 | \$50.00 | 0024-8517 | 0024-8518 |
| 0024-7260 | FYRITE PRO-120 (Limited Repair) | Obsolete Model - Consider Replacing | | | \$725.00 | \$100.00 | \$50.00 | 0024-8517 | 0024-8518 |
| 0024-7268 | FYRITE PRO-125 (Limited Repair) | Obsolete Model - Consider Replacing | | | \$725.00 | \$100.00 | \$50.00 | 0024-8517 | 0024-8518 |
| 0024-7269 | FYRITE PRO-105 (Limited Repair) | Obsolete Model - Consider Replacing | | | \$725.00 | \$100.00 | \$50.00 | 0024-8517 | 0024-8518 |
| 0024-7270 | FYRITE PRO-100 (Limited Repair) | Obsolete Model - Consider Replacing | | | \$725.00 | \$100.00 | \$50.00 | 0024-8517 | 0024-8518 |
| 0024-7275 | FYRITE PRO 125F (Limited Repair) | Obsolete Model - Consider Replacing | | | \$725.00 | \$100.00 | \$50.00 | 0024-8521 | 0024-8520 |
| 0024-7276 | FYRITE PRO 125E - EU (Limited Repair) | Obsolete Model - Consider Replacing | | | \$725.00 | \$100.00 | \$50.00 | 0024-8521 | 0024-8520 |
| 0024-7279 | FYRITE PRO 125I (Limited Repair) | Obsolete Model - Consider Replacing | | | \$725.00 | \$100.00 | \$50.00 | 0024-8521 | 0024-8520 |



Effective 1/1/2019 Rev. 0

Please call for instrument part numbers not included in this list. Service may no longer be available or we can suggest a replacement.

** 24 hour Priority Service is only available for items listed below. Priority Service orders MUST (1) include a pre-approved amount, (2) include the RMA paperwork and (3) a PRIORITY label on the outside of the package. Returns received without this information will cause delays in processing your order. 24 hrs begins when the instrument is received at our facility during regular business hours Monday through Friday. Return shipping and handling charges will be added to the order unless directed to ship collect or billed to a 3rd party account in which case only a handling charge will apply. AQMD testing is not available for Priority Service. **

| Instrument Information | | Repair Fees | | | | Optional | | Current | |
|------------------------|----------------------------|-------------------------------------|---------------------------------|--|---------------------------------|--|----------------------------|-----------------------|--------------|
| Part Number | Model | Functional Test (Min) | Standard Calibration Only (Min) | Standard Calibration Plus 1 Sensor (Typical) | Not to Exceed (Max Preapproved) | NIST Certificate (Before & After Readings) | **24 Hour Priority Service | Suggested Replacement | With Printer |
| 0024-7281 | PCA-10 EU (Limited Repair) | Last Day of Service June 30, 2019 | | | \$850.00 | \$100.00 | \$50.00 | 0024-8513 | 0024-8514 |
| 0024-7282 | PCA-15 EU (Limited Repair) | Last Day of Service June 30, 2019 | | | \$850.00 | \$100.00 | \$50.00 | 0024-8521 | 0024-8522 |
| 0024-7283 | PCA-20 EU (Limited Repair) | Last Day of Service June 30, 2019 | | | \$850.00 | \$100.00 | \$50.00 | 0024-8513 | 0024-8514 |
| 0024-7284 | PCA-25 EU (Limited Repair) | Last Day of Service June 30, 2019 | | | \$850.00 | \$100.00 | \$50.00 | 0024-8521 | 0024-8522 |
| 0024-7285 | PCA-30 EU (Limited Repair) | Last Day of Service June 30, 2019 | | | \$850.00 | \$100.00 | \$50.00 | 2411-1110 | 2411-1112 |
| 0024-7286 | PCA-35 EU (Limited Repair) | Last Day of Service June 30, 2019 | | | \$850.00 | \$100.00 | \$50.00 | 2411-1110 | 2411-1112 |
| 0024-7289 | ECA450 | N/A | \$345.00 | \$655.00 | \$1,400.00 | \$100.00 | \$50.00 | N/A | N/A |
| 0024-7301 | PCA2-225 (Limited Repair) | Obsolete Model - Consider Replacing | | | \$850.00 | \$100.00 | \$50.00 | 0024-8517 | 0024-8518 |
| 0024-7302 | PCA2-235 (Limited Repair) | Obsolete Model - Consider Replacing | | | \$850.00 | \$100.00 | \$50.00 | 0024-1110 | 2411-1112 |
| 0024-7303 | PCA2-245 (Limited Repair) | Obsolete Model - Consider Replacing | | | \$850.00 | \$100.00 | \$50.00 | 2420-1110 | 2420-1112 |
| 0024-7304 | PCA2-255 (Limited Repair) | Obsolete Model - Consider Replacing | | | \$850.00 | \$100.00 | \$50.00 | 2414-1310 | 2414-1312 |
| 0024-7305 | PCA2-265 (Limited Repair) | Obsolete Model - Consider Replacing | | | \$850.00 | \$100.00 | \$50.00 | 2412-1310 | 2412-1312 |
| 0024-7306 | PCA2-275 (Limited Repair) | Obsolete Model - Consider Replacing | | | \$850.00 | \$100.00 | \$50.00 | 2413-1310 | 2413-1312 |
| 0024-7307 | PCA2-285 (Limited Repair) | Obsolete Model - Consider Replacing | | | \$850.00 | \$100.00 | \$50.00 | 2421-1110 | 2421-1112 |
| 0024-7308 | FYRITE INSIGHT | N/A | \$150.00 | \$275.00 | \$725.00 | \$100.00 | \$50.00 | 0024-8517 | 0024-8518 |
| 0024-7309 | FYRITE INSIGHT - SIEGERT | N/A | \$150.00 | \$275.00 | \$725.00 | \$100.00 | \$50.00 | 0024-8521 | 0024-8522 |
| 0024-7311 | FYRITE INSIGHT - DANISH | N/A | \$150.00 | \$275.00 | \$725.00 | \$100.00 | \$50.00 | 0024-8521 | 0024-8522 |
| 0024-7320 | PCA3-225 O2 & CO | N/A | \$190.00 | \$410.00 | \$750.00 | \$100.00 | \$50.00 | 0024-8517 | 0024-8518 |
| 0024-7321 | PCA3-235 O2, CO & NO | N/A | \$190.00 | \$410.00 | \$750.00 | \$100.00 | \$50.00 | 2411-1110 | 2411-1112 |
| 0024-7322 | PCA3-245 O2, CO & COH | N/A | \$190.00 | \$410.00 | \$750.00 | \$100.00 | \$50.00 | 2420-1110 | 2420-1112 |
| 0024-7323 | PCA3-255 O2, CO, & SO2 | N/A | \$190.00 | \$410.00 | \$750.00 | \$100.00 | \$50.00 | 2414-1310 | 2414-1312 |
| 0024-7324 | PCA3-265 O2, CO, NO & NO2 | N/A | \$190.00 | \$410.00 | \$750.00 | \$100.00 | \$50.00 | 2412-1310 | 2412-1312 |
| 0024-7325 | PCA3-275 O2, CO, NO & SO2 | N/A | \$190.00 | \$410.00 | \$750.00 | \$100.00 | \$50.00 | 2413-1310 | 2413-1312 |
| 0024-7326 | PCA3-285 O2, CO, NO, COH | N/A | \$190.00 | \$410.00 | \$750.00 | \$100.00 | \$50.00 | 2421-1110 | 2421-1112 |



Effective 1/1/2019 Rev. 0

Please call for instrument part numbers not included in this list. Service may no longer be available or we can suggest a replacement.

** 24 hour Priority Service is only available for items listed below. Priority Service orders MUST (1) include a pre-approved amount, (2) include the RMA paperwork and (3) a PRIORITY label on the outside of the package. Returns received without this information will cause delays in processing your order. 24 hrs begins when the instrument is received at our facility during regular business hours Monday through Friday. Return shipping and handling charges will be added to the order unless directed to ship collect or billed to a 3rd party account in which case only a handling charge will apply. AQMD testing is not available for Priority Service. **

| Instrument Information | | Repair Fees | | | | Optional | | Current | |
|------------------------|--------------------------------|-----------------------|---------------------------------|--|---------------------------------|--|----------------------------|-----------------------|--------------|
| Part Number | Model | Functional Test (Min) | Standard Calibration Only (Min) | Standard Calibration Plus 1 Sensor (Typical) | Not to Exceed (Max Preapproved) | NIST Certificate (Before & After Readings) | **24 Hour Priority Service | Suggested Replacement | With Printer |
| 0024-7327 | PCA3 DANISH | N/A | \$190.00 | \$410.00 | \$750.00 | \$100.00 | \$50.00 | N/A | N/A |
| 0024-7328 | PCA3-295 O2, CO, NO2, SO2 | N/A | \$190.00 | \$410.00 | \$750.00 | \$100.00 | \$50.00 | 2413-1310 | 2413-1312 |
| 0024-7330 | PCA3-225 - SIEGERT | N/A | \$190.00 | \$410.00 | \$750.00 | \$100.00 | \$50.00 | 0024-8521 | 0024-8522 |
| 0024-7331 | PCA3-235 - SIEGERT | N/A | \$190.00 | \$410.00 | \$750.00 | \$100.00 | \$50.00 | 2411-1110 | 2411-1112 |
| 0024-7332 | PCA3-245 - SIEGERT | N/A | \$190.00 | \$410.00 | \$750.00 | \$100.00 | \$50.00 | 2420-1110 | 2420-1112 |
| 0024-7333 | PCA3-255 - SEIGERT | N/A | \$190.00 | \$410.00 | \$750.00 | \$100.00 | \$50.00 | 2414-1310 | 2414-1312 |
| 0024-7334 | PCA3-265 - SEIGERT | N/A | \$190.00 | \$410.00 | \$750.00 | \$100.00 | \$50.00 | 2412-1310 | 2412-1312 |
| 0024-7335 | PCA3-275 - SEIGERT | N/A | \$190.00 | \$410.00 | \$750.00 | \$100.00 | \$50.00 | 2413-1310 | 2413-1312 |
| 0024-7336 | PCA3-285 - SEIGERT | N/A | \$190.00 | \$410.00 | \$750.00 | \$100.00 | \$50.00 | 2421-1110 | 2421-1112 |
| 0024-7337 | PCA3-295 - SEIGERT | N/A | \$190.00 | \$410.00 | \$750.00 | \$100.00 | \$50.00 | 2413-1310 | 2413-1312 |
| 0024-7340 | FYRITE INTECH | N/A | \$145.00 | \$270.00 | \$354.00 | \$100.00 | \$50.00 | N/A | N/A |
| 0024-7341 | FYRITE INTECH | N/A | \$145.00 | \$270.00 | \$354.00 | \$100.00 | \$50.00 | N/A | N/A |
| 0024-7342 | FYRITE INTECH - EUROPEAN | N/A | \$145.00 | \$270.00 | \$354.00 | \$100.00 | \$50.00 | N/A | N/A |
| 0024-7343 | FYRITE INSIGHT PLUS | N/A | \$145.00 | \$270.00 | \$714.00 | \$100.00 | \$50.00 | N/A | N/A |
| 0024-7344 | FYRITE INSIGHT PLUS | N/A | \$145.00 | \$270.00 | \$714.00 | \$100.00 | \$50.00 | N/A | N/A |
| 0024-7345 | FYRITE INSIGHT PLUS - EUROPEAN | N/A | \$145.00 | \$270.00 | \$714.00 | \$100.00 | \$50.00 | N/A | N/A |
| 0024-7346 | FYRITE INSIGHT PLUS - EUROPEAN | N/A | \$145.00 | \$270.00 | \$714.00 | \$100.00 | \$50.00 | N/A | N/A |
| 0024-7349 | FYRITE INSIGHT PLUS - DANISH | N/A | \$145.00 | \$270.00 | \$714.00 | \$100.00 | \$50.00 | N/A | N/A |
| 0024-7350 | PCA-400 | N/A | \$185.00 | \$400.00 | \$724.00 | \$100.00 | \$50.00 | N/A | N/A |
| 0024-7351 | PCA-400 | N/A | \$185.00 | \$400.00 | \$724.00 | \$100.00 | \$50.00 | N/A | N/A |
| 0024-7352 | PCA-400 | N/A | \$185.00 | \$400.00 | \$724.00 | \$100.00 | \$50.00 | N/A | N/A |
| 0024-7353 | PCA-400 | N/A | \$185.00 | \$400.00 | \$724.00 | \$100.00 | \$50.00 | N/A | N/A |
| 0024-7354 | PCA-400 | N/A | \$185.00 | \$400.00 | \$724.00 | \$100.00 | \$50.00 | N/A | N/A |
| 0024-7355 | PCA-400 | N/A | \$185.00 | \$400.00 | \$724.00 | \$100.00 | \$50.00 | N/A | N/A |



Effective 1/1/2019 Rev. 0

Please call for instrument part numbers not included in this list. Service may no longer be available or we can suggest a replacement.

** 24 hour Priority Service is only available for items listed below. Priority Service orders MUST (1) include a pre-approved amount, (2) include the RMA paperwork and (3) a PRIORITY label on the outside of the package. Returns received without this information will cause delays in processing your order. 24 hrs begins when the instrument is received at our facility during regular business hours Monday through Friday. Return shipping and handling charges will be added to the order unless directed to ship collect or billed to a 3rd party account in which case only a handling charge will apply. AQMD testing is not available for Priority Service. **

| Instrument Information | | Repair Fees | | | | Optional | | Current | |
|------------------------|--------------------------|-------------------------------------|---------------------------------|--|---------------------------------|--|----------------------------|-----------------------|--------------|
| Part Number | Model | Functional Test (Min) | Standard Calibration Only (Min) | Standard Calibration Plus 1 Sensor (Typical) | Not to Exceed (Max Preapproved) | NIST Certificate (Before & After Readings) | **24 Hour Priority Service | Suggested Replacement | With Printer |
| 0024-7356 | PCA-400 | N/A | \$185.00 | \$400.00 | \$724.00 | \$100.00 | \$50.00 | N/A | N/A |
| 0024-7357 | PCA-400 | N/A | \$185.00 | \$400.00 | \$724.00 | \$100.00 | \$50.00 | N/A | N/A |
| 0024-7358 | PCA-400 | N/A | \$185.00 | \$400.00 | \$724.00 | \$100.00 | \$50.00 | N/A | N/A |
| 0024-7359 | PCA-400 | N/A | \$185.00 | \$400.00 | \$724.00 | \$100.00 | \$50.00 | N/A | N/A |
| 2000-3600 | FM3600 (Limited Repair) | Obsolete Model - Consider Replacing | | | \$999.00 | N/A | N/A | 2020-8000 | N/A |
| 2000-3611 | FM3600 (Limited Repair) | Obsolete Model - Consider Replacing | | | \$999.00 | N/A | N/A | 2020-8001 | N/A |
| 2000-3700 | FM3700 (Limited Repair) | Obsolete Model - Consider Replacing | | | \$999.00 | N/A | N/A | 2020-8000 | N/A |
| 2000-3701 | FM3700 (Limited Repair) | Obsolete Model - Consider Replacing | | | \$1,099.00 | N/A | N/A | 2020-8001 | N/A |
| 2020-8000 | ECO2020 | Return for Estimate | | | \$450.00 | N/A | N/A | N/A | N/A |
| 2020-8001 | ECO2020 | Return for Estimate | | | \$450.00 | N/A | N/A | N/A | N/A |
| 3015-0456 | H10G | Obsolete Model - Consider Replacing | | | N/A | N/A | N/A | 3015-8004 | N/A |
| 3015-0462 | H10G | Obsolete Model - Consider Replacing | | | N/A | N/A | N/A | 3015-8004 | N/A |
| 3015-0480 | H10G | Obsolete Model - Consider Replacing | | | N/A | N/A | N/A | 3015-8004 | N/A |
| 3015-0627 | H10PM (Limited Repair) | Obsolete Model - Consider Replacing | | | N/A | N/A | N/A | 3015-8004 | N/A |
| 3015-0630 | H10PM (Limited Repair) | Obsolete Model - Consider Replacing | | | N/A | N/A | N/A | 3015-8004 | N/A |
| 3015-0636 | H10PM (Limited Repair) | Obsolete Model - Consider Replacing | | | N/A | N/A | N/A | 3015-8004 | N/A |
| 3015-4200 | SINGLE-ZONE HGMSZ | N/A | \$225.00 | N/A | \$1,200.00 | \$100.00 | N/A | N/A | N/A |
| 3015-4316 | SINGLE-ZONE HGMSZ | N/A | \$225.00 | N/A | \$1,200.00 | \$100.00 | N/A | N/A | N/A |
| 3015-4348 | H25IR | N/A | \$475.00 | N/A | \$1,100.00 | \$100.00 | N/A | H25IR-PRO | N/A |
| 3015-4484 | PORTABLE GAS MONITOR-HGM | N/A | \$250.00 | N/A | \$1,100.00 | \$100.00 | N/A | N/A | N/A |
| 3015-4790 | PORTABLE GAS MONITOR-N2O | N/A | \$250.00 | N/A | \$1,100.00 | \$100.00 | N/A | N/A | N/A |
| 3015-5043 | MULTI-ZONE HGMMZ | N/A | \$250.00 | N/A | \$1,400.00 | \$100.00 | N/A | N/A | N/A |
| 3015-5044 | MULTI-ZONE HGMMZ | N/A | \$250.00 | N/A | \$1,400.00 | \$100.00 | N/A | N/A | N/A |
| 3015-5045 | MULTI-ZONE HGMMZ | N/A | \$250.00 | N/A | \$1,400.00 | \$100.00 | N/A | N/A | N/A |



Effective 1/1/2019 Rev. 0

Please call for instrument part numbers not included in this list. Service may no longer be available or we can suggest a replacement.

** 24 hour Priority Service is only available for items listed below. Priority Service orders MUST (1) include a pre-approved amount, (2) include the RMA paperwork and (3) a PRIORITY label on the outside of the package. Returns received without this information will cause delays in processing your order. 24 hrs begins when the instrument is received at our facility during regular business hours Monday through Friday. Return shipping and handling charges will be added to the order unless directed to ship collect or billed to a 3rd party account in which case only a handling charge will apply. AQMD testing is not available for Priority Service. **

| Instrument Information | | Repair Fees | | | | Optional | | Current | |
|------------------------|--------------------------|-----------------------|---------------------------------|--|---------------------------------|--|----------------------------|-----------------------|--------------|
| Part Number | Model | Functional Test (Min) | Standard Calibration Only (Min) | Standard Calibration Plus 1 Sensor (Typical) | Not to Exceed (Max Preapproved) | NIST Certificate (Before & After Readings) | **24 Hour Priority Service | Suggested Replacement | With Printer |
| 3015-5046 | MULTI-ZONE HGMMZ | N/A | \$250.00 | N/A | \$1,400.00 | \$100.00 | N/A | N/A | N/A |
| 3015-5138 | MZ REMOTE DISPLAY HGMRD | N/A | N/A | N/A | \$699.00 | N/A | N/A | N/A | N/A |
| 3015-5200 | MULTI-ZONE HGMMZ | N/A | \$250.00 | N/A | \$1,400.00 | \$100.00 | N/A | N/A | N/A |
| 3015-5201 | MULTI-ZONE HGMMZ | N/A | \$250.00 | N/A | \$1,400.00 | \$100.00 | N/A | N/A | N/A |
| 3015-5202 | MULTI-ZONE HGMMZ | N/A | \$250.00 | N/A | \$1,400.00 | \$100.00 | N/A | N/A | N/A |
| 3015-5203 | MULTI-ZONE HGMMZ | N/A | \$250.00 | N/A | \$1,400.00 | \$100.00 | N/A | N/A | N/A |
| 3015-5211 | MULTI-ZONE HGMMZ | N/A | \$250.00 | N/A | \$1,400.00 | \$100.00 | N/A | N/A | N/A |
| 3015-5213 | MULTI-ZONE HGMMZ | N/A | \$250.00 | N/A | \$1,400.00 | \$100.00 | N/A | N/A | N/A |
| 3015-5260 | H25IR | N/A | \$475.00 | N/A | \$1,100.00 | \$100.00 | N/A | H25IR-PRO | N/A |
| 3015-5330 | MULTI-ZONE HGMMZ | N/A | \$250.00 | N/A | \$1,400.00 | \$100.00 | N/A | N/A | N/A |
| 3015-5333 | MULTI-ZONE HGMMZ | N/A | \$250.00 | N/A | \$1,400.00 | \$100.00 | N/A | N/A | N/A |
| 3015-5560 | MULTI-ZONE HGMMZ | N/A | \$250.00 | N/A | \$1,400.00 | \$100.00 | N/A | N/A | N/A |
| 3015-5570 | MULTI-ZONE HGMMZ | N/A | \$250.00 | N/A | \$1,400.00 | \$100.00 | N/A | N/A | N/A |
| 3015-5600 | H25IR-PRO | N/A | \$475.00 | N/A | \$1,200.00 | \$100.00 | N/A | N/A | N/A |
| 3015-5696 | PORTABLE GAS MONITOR-HGM | N/A | \$250.00 | N/A | \$1,100.00 | \$100.00 | N/A | N/A | N/A |
| 3015-5720 | PORTABLE GAS MONITOR-HGM | N/A | \$250.00 | N/A | \$1,100.00 | \$100.00 | N/A | N/A | N/A |
| 3015-5732 | MULTI-ZONE HGMMZ | N/A | \$250.00 | N/A | \$1,400.00 | \$100.00 | N/A | N/A | N/A |
| 3015-5734 | MULTI-ZONE HGMMZ | N/A | \$250.00 | N/A | \$1,400.00 | \$100.00 | N/A | N/A | N/A |
| 3015-5751 | PORTABLE GAS MONITOR-CO2 | N/A | \$250.00 | N/A | \$1,400.00 | \$100.00 | N/A | N/A | N/A |
| 3015-5835 | H25IR-PRO | N/A | \$475.00 | N/A | \$1,100.00 | \$100.00 | N/A | N/A | N/A |
| 3015-7000 | H10PRO | \$60.00 | N/A | \$225.00 | \$305.00 | N/A | \$50.00 | N/A | N/A |
| 3019-8101 | MULTI-ZONE HGMMZ | N/A | \$250.00 | N/A | \$1,100.00 | \$100.00 | N/A | N/A | N/A |
| 5110-0100 | ODOROMETER | N/A | \$300.00 | N/A | \$400.00 | \$100.00 | N/A | N/A | N/A |
| 5110-0200 | ODOROMETER | N/A | \$300.00 | N/A | \$400.00 | \$100.00 | N/A | N/A | N/A |